

All Locations Report

Building **906700241753** **30 Bengal Street**
Sampling (T2) on 14-10-2004

Room	B1/BH01	Boilerhouse		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	Thermal Insulation			9
All Equipment	Textiles Gaskets			3
Skylight	No Suspect Material			0
Boilerhouse debris	Asbestos Reinforced Composites			5

Room	B1/BH01/1	Boilerhouse		
Location	ACM	Material	Comments	Material Score
Piping	Thermal Insulation			9
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	B1/BH01/2	Boilerhouse		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0

Room	Building			
Location	ACM	Material	Comments	Material Score
ATTIC	Cement Asbestos			8

Room	Ext/Ex01	Room		
Location	ACM	Material	Comments	Material Score
Sarking felt 1	No Suspect Material		Identified.	0
Sarking felt 2	No Suspect Material		Identified.	0

Room	F1/A01	Open Area		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators	No Suspect Material			0

Room	F1/C01	Corridor		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F1/C02	Corridor		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F1/R01	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators	No Suspect Material			0

Room	F1/R02	Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Cooker	Textiles Gaskets			3
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Sink pad	Asbestos Reinforced Composites			2

Room	F1/R02/1	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators	No Suspect Material			0

Room	F1/R02/2	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material		Open, no ceiling.	0

Room	F1/R02/3	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Plumbing goods	No Suspect Material	0
----------------	---------------------	---

Room Location	F1/R03 ACM	Room Material	Comments	Material Score
Piping	No Suspect Material			0
Radiators	No Suspect Material			0
Sink Pad	Asbestos Reinforced Composites			2
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room Location	F1/R04 ACM	Room Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators	No Suspect Material			0

Room Location	F1/R05 ACM	Room Material	Comments	Material Score
Vent. equip.	No Suspect Material			0
Extract fan	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Plumbing goods	No Suspect Material			0

Room Location	F1/R05/1 ACM	Room Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Equipment	No Suspect Material			0

Room Location	F1/R06 ACM	Room Material	Comments	Material Score
Radiators	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Plumbing goods	No Suspect Material			0
Piping	No Suspect Material			0

Building 906700241753 30 Bengal Street
Sampling (T2) on 14-10-2004

Room	F1/R07	Room		
Location	ACM	Material	Comments	Material Score
Ceiling voids	No Suspect Material			0
Sink pad	Asbestos Reinforced Composites			2
Piping	No Suspect Material			0
Radiators	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling tiles	No Suspect Material			0

Room	F1/R08	Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Radiators	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material		Confirmed by analysis	0
Ceiling voids	No Suspect Material			0
Ceiling tiles	No Suspect Material			0

Room	F1/R09	Room		
Location	ACM	Material	Comments	Material Score
Ceiling tiles	No Suspect Material			0
Sink unit	Asbestos Reinforced Composites			3
Piping	No Suspect Material			0
Radiators	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling voids	No Suspect Material			0

Room	F1/R10	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling tiles	No Suspect Material			0
Piping	No Suspect Material			0
Ceiling void	No Suspect Material			0
Sink/drain pad	No Suspect Material			0
Radiators	No Suspect Material			0

Room	F1/R11	Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Radiators/heater	No Suspect Material			0
Heating	No Suspect Material			0

Building 906700241753 30 Bengal Street
Sampling (T2) on 14-10-2004

Ceiling tiles	No Suspect Material		0
Walls 1-4	No Suspect Material		0
Floor	No Suspect Material		0
Ceiling voids	No Suspect Material		0

Room	F1/R12	Toilet		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Cistern	No Suspect Material			0
Radiators	No Suspect Material			0

Room	F1/R13	Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Fan Unit Wall 2	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Plumbing goods	No Suspect Material			0

Room	F1/R13/1	Room		
Location	ACM	Material	Comments	Material Score
Wall 1	No Suspect Material			0
Wall 2	No Suspect Material			0
Wall 3	No Suspect Material			0
Wall 4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators/heater	No Suspect Material			0
Plumbing goods	No Suspect Material			0

Room	F1/SW01	Stairwell		
Location	ACM	Material	Comments	Material Score
Sink	No Suspect Material			0
Piping	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F1/SW02	Stairwell		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Ceiling	No Suspect Material	0
Piping	No Suspect Material	0
Electrical equipment	Textiles Gaskets	3

Room	F1/TR01	Tank Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Equipment	No Suspect Material			0

Room	F1/TR02	Tank Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Equipment	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F2/A01	Open Area		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Skylights	No Suspect Material			0
Piping n2	No Suspect Material			0

Room	F2/C01	Corridor		
Location	ACM	Material	Comments	Material Score
Skylights	No Suspect Material			0
Floor tiles	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F2/C02	Corridor		
Location	ACM	Material	Comments	Material Score
Floor	Asbestos Reinforced Composites			3
Wall 1-4	No Suspect Material			0
Ceiling	No Suspect Material			0
Skylights	No Suspect Material			0

Room	F2/R01	Room		
Location	ACM	Material	Comments	Material Score

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Walls 1-4	No Suspect Material	0
Floor	No Suspect Material	0
Ceiling	No Suspect Material	0

Room	F2/R03	Room		
Location	ACM	Material	Comments	Material Score
Ceiling	No Suspect Material			0
Wall 1-4	No Suspect Material			0
Radiators	No Suspect Material			0
Piping	No Suspect Material			0
Floor	No Suspect Material		Confirmed by analysis.	0
Sink pad	Asbestos Reinforced Composites			2

Room	F2/R04	Room		
Location	ACM	Material	Comments	Material Score
Radiators/heater	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material		Confirmed by analysis	0

Room	F2/R05	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators/heater	No Suspect Material			0

Room	F2/R06	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F2/R07	Store		
Location	ACM	Material	Comments	Material Score
Wall 1	No Suspect Material			0
Wall 2	No Suspect Material			0
Wall 3	No Suspect Material			0
Wall 4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0

Room	F2/R07/1	Room		
-------------	-----------------	-------------	--	--

Building 906700241753 30 Bengal Street
Sampling (T2) on 14-10-2004

Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators/heater	Textiles Gaskets			3

Room F2/R08

Room

Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Plumbing goods	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room F2/R09

Room

Location	ACM	Material	Comments	Material Score
Sink pad	Asbestos Reinforced Composites			2
Piping	No Suspect Material			0
Radiators/heater	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room F2/R09/1

Room

Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Sink Pad	Asbestos Reinforced Composites			2
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room F2/R10

Room

Location	ACM	Material	Comments	Material Score
Radiators/heater	No Suspect Material			0
Piping	No Suspect Material			0
Sink/drain pad	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room F2/R11

Room

Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Ceiling	No Suspect Material	0
Piping	No Suspect Material	0

Room	F2/R11/1	Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Sink Unit	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Radiators	No Suspect Material			0

Room	F2/R12	Room		
Location	ACM	Material	Comments	Material Score
Radiators	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Sink/drainer pad	No Suspect Material			0

Room	F2/R13	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F2/R13/1	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators/heater	No Suspect Material			0

Room	F2/R14	Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Radiators/heater	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F2/R15	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Ceiling	No Suspect Material	0
Piping	No Suspect Material	0
Radiators/heater	No Suspect Material	0
Plumbing goods	No Suspect Material	0

Room	F2/R16	Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Radiators/heater	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F2/TR03	Tank Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Equipment	No Suspect Material			0

Room	F2/TR04	Tank Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Equipment	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	F3/RS01	Roofspace		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material		Confirmed by analysis	0
Ceiling	No Suspect Material			0
Piping insulation	No Suspect Material	Stud Partition	Confirmed by analysis.	0

Room	F3/RS02	Roofspace		
Location	ACM	Material	Comments	Material Score
Piping insulation	No Suspect Material	Concrete/Plaster	Confirmed by analysis.	0
Piping	No Suspect Material		Confirmed by analysis.	0
Walls 1-4	No Suspect Material			0
Floor	Thermal Insulation		Asbestos confirmed by analysis	9
Ceiling	No Suspect Material			0

Room	F3/RS03	Roofspace		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Floor	No Suspect Material	Confirmed by analysis	0
Ceiling	No Suspect Material		0
Piping	No Suspect Material		0

Room	F3/RS04	Roofspace		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material		Confirmed by analysis	0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material		Confirmed by analysis.	0
Ceiling	No Suspect Material			0

Room	F3/RS05	Roofspace		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material		Confirmed by analysis.	0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Equipment	No Suspect Material			0

Room	F3/RS06	Roofspace		
Location	ACM	Material	Comments	Material Score
Piping	Thermal Insulation			10
Vent. Unit	Textiles Gaskets			3
Walls 1-4	No Suspect Material			0
Floor	Thermal Insulation		Asbestos confirmed by analysis	10
Ceiling	No Suspect Material			0

Room	F3/RS07	Roofspace		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	Thermal Insulation		Asbestos confirmed by analysis	10
Ceiling	No Suspect Material			0
Wall 4	Asbestos Board		Asbestos confirmed by analysis	7
Piping	No Suspect Material		Confirmed by analysis	0
Piping insulation	No Suspect Material	Concrete/Plaster		0

Room	F3/RS08	Roofspace		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material		Confirmed by analysis.	0
Equipment	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material		Confirmed by analysis	0
Ceiling	No Suspect Material			0

Room	F3/RS09	Roofspace		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0

Building	906700241753	30 Bengal Street		
	Sampling (T2) on 14-10-2004			

Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping insulation	No Suspect Material	Concrete/Plaster		0
Floor debris	Thermal Insulation		Asbestos confirmed by analysis	11
Piping	No Suspect Material		Confirmed by analysis	0
Tank	No Suspect Material		Asbestos confirmed by analysis	0

Room	G/A01	Open Area		
Location	ACM	Material	Comments	Material Score
Radiators/heater	No Suspect Material			0
Piping	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	G/A02	Open Area		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators Walls 1 and, 2 and, 3	No Suspect Material			0

Room	G/A03	Open Area		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling tiles	No Suspect Material	Stud Partition		0
Ceiling void	No Suspect Material			0

Room	G/A04	Open Area		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Ceiling	No Suspect Material			0
Radiators Walls 2 and, 3	No Suspect Material			0
Floor	No Suspect Material	Brick		0

Room	G/C01	Corridor		
Location	ACM	Material	Comments	Material Score
Floor	Asbestos Reinforced Composites	Brick/Plaster		3
Wall 1-4	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	G/E01	Entrance		
Location	ACM	Material	Comments	Material Score

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Piping	No Suspect Material	0
Walls 1-4	No Suspect Material	0
Floor	No Suspect Material	0
Ceiling	No Suspect Material	0
Radiators Walls 1 and, 2	No Suspect Material	0

Room	G/E02	Entrance		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	G/R01	Toilet		
Location	ACM	Material	Comments	Material Score
Floor tiles	Asbestos Reinforced Composites	Brick/Plaster		4
Walls 1-4	No Suspect Material			0
Ceiling	No Suspect Material			0
Radiators	No Suspect Material			0
Piping	No Suspect Material			0
Plumbing goods	No Suspect Material			0

Room	G/R02	Room		
Location	ACM	Material	Comments	Material Score
Vent equipment	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	G/R02/1	Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Plumbing goods	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Cast iron pipe	No Suspect Material		Preformed plastic products; Unlikely to release fibres	0

Room	G/R03	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0

Room	G/R03/1	Room		
Location	ACM	Material	Comments	Material Score

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Piping	No Suspect Material	0
Walls 1-4	No Suspect Material	0
Floor	No Suspect Material	0
Ceiling	No Suspect Material	0

Room	G/R04	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Radiators Wall 4	No Suspect Material			0

Room	G/R05	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Sink	No Suspect Material			0

Room	G/R06	Room		
Location	ACM	Material	Comments	Material Score
Ceiling void	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling tiles	No Suspect Material	Stud Partition		0

Room	G/R06/1	Toilet		
Location	ACM	Material	Comments	Material Score
Ceiling tiles	No Suspect Material	Stud Partition		0
Pipework	No Suspect Material			0
Plumbing goods	No Suspect Material			0
Vent equipment	No Suspect Material			0
Cistern	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0

Room	G/R06/2	Toilet		
Location	ACM	Material	Comments	Material Score
Cistern	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Ceiling void	No Suspect Material			0
Sink pad	Asbestos Reinforced Composites			2
Plumbing goods	No Suspect Material			0
Vent equipment	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Floor	No Suspect Material			0
Ceiling tiles	No Suspect Material	Stud Partition		0
Room	G/R07	Office		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Ceiling void	No Suspect Material			0
Radiators Wall 3	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Radiators shelf	Asbestos Board	Brick/Plaster		6
Ceiling	No Suspect Material			0
Room	G/R08	Room		
Location	ACM	Material	Comments	Material Score
Radiators Walls 2 and, 3	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Sink unit	Asbestos Reinforced Composites			3
Room	G/R09	Kitchen		
Location	ACM	Material	Comments	Material Score
Vent equipment	No Suspect Material			0
Piping	No Suspect Material			0
Electrical equipment	Textiles Gaskets			3
Walls 1-4	No Suspect Material			0
Ceiling	No Suspect Material			0
Immensor	Textiles Gaskets		Textiles/Gaskets: Unlikely to release fibres, unless being replaced	3
Sink/drainer pad	No Suspect Material	Brick		0
Floor	Asbestos Reinforced Composites	Brick		3
Room	G/R10	Room		
Location	ACM	Material	Comments	Material Score
Radiators Wall 3	No Suspect Material			0
Piping	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Room	G/R11	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Floor	No Suspect Material		0
Ceiling	No Suspect Material		0
Electrical equip	Textiles Gaskets		3

Room	G/R12	Toilet		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	Thermal Insulation			8
Fan Unit Wall 4	No Suspect Material			0
Floor	Asbestos Reinforced Composites	Brick		3
Plumbing goods	No Suspect Material			0

Room	G/R13	Toilet		
Location	ACM	Material	Comments	Material Score
Cistern	No Suspect Material	Brick/Plaster		0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators Wall 4	No Suspect Material			0
Vertical Duct Wall 1 N/A	No Suspect Material			0

Room	G/R14	Room		
Location	ACM	Material	Comments	Material Score
Piping	No Suspect Material			0
Radiators Walls 2 and, 3	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	G/R15	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Radiators Walls 3 and, 4	No Suspect Material			0
Piping	No Suspect Material			0
Radiators Walls 2 and, 3	No Suspect Material			0

Room	G/R16	Classroom		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Radiators Walls 3 and, 4	No Suspect Material			0
Sink/drainer pad	Asbestos Reinforced Composites	Brick		3
Room	G/SW01	Stairwell		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Room	G/SW02	Stairwell		
Location	ACM	Material	Comments	Material Score
Distribution board on Wall 3	Textiles Gaskets			3
Wall 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Room	Mez1/C01	Corridor		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Room	Mez1/R01	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators	No Suspect Material			0
Extract fan	No Suspect Material			0
Room	Mez1/R01/1	Room		
Location	ACM	Material	Comments	Material Score
Plumbing goods	No Suspect Material			0
Gas water heater	Textiles Gaskets			3
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Room	Mez1/R01/2	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Room	Mez1/R02	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Equipment	No Suspect Material			0

Room	Mez2/C01	Corridor		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0

Room	Mez2/R01	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators	No Suspect Material			0

Room	Mez2/R01/1	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0

Room	Mez2/R01/2	Room		
Location	ACM	Material	Comments	Material Score
Plumbing goods	No Suspect Material			0
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0

Room	Mez3/R01	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators	No Suspect Material			0
Fireplace panel	Asbestos Board			5

Building	906700241753	30 Bengal Street
	Sampling (T2) on 14-10-2004	

Sink unit	Asbestos Reinforced Composites	2
-----------	--------------------------------	---

Room	Mez3/R01/1	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Plumbing goods	No Suspect Material			0

Room	Mez4/R01	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Radiators	No Suspect Material			0
Fireplace panel	Asbestos Board			5

Room	Mez4/R01/1	Room		
Location	ACM	Material	Comments	Material Score
Walls 1-4	No Suspect Material			0
Floor	No Suspect Material			0
Ceiling	No Suspect Material			0
Piping	No Suspect Material			0
Plumbing goods	No Suspect Material			0

End of Building